

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

DZ628  
WSW  
1/2-1  
0.928 mi.  
4901 ft.

VAULT ZS5234  
2900 MERMAID AVE  
BROOKLYN, NY  
Site 4 of 4 in cluster DZ

NY Spills S119028671  
N/A

Relative:  
Higher

Actual:  
3 ft.

SPILLS:

Name: VAULT ZS5234  
Address: 2900 MERMAID AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1608681 / 2017-10-03  
Facility ID: 1608681  
Facility Type: ER  
DER Facility ID: 491292  
Site ID: 537411  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2016-12-11  
Investigator: RWAUSTIN  
Referred To: Not reported  
Reported to Dept: 2016-12-11  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Transformer  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2016-12-11  
Spill Record Last Update: 2017-10-03  
Spiller Name: TIM REAGAN  
Spiller Company: CON ED  
Spiller Address: 2900 MERMAID AVE  
Spiller Company: 999  
Contact Name: TIM REAGAN  
DEC Memo: "10/3/17 - Austin - While conducting a transformer replacement, Con Ed found 5 oz oil atop 500 gals water in vault - Con Ed removed the transformer and contained and cleaned up the spill; no oil seen after cleaning - See document files for further information - Spill closed  
- end"

Remarks: "Vault makes water. Spill to the water. Clean up pending."

All Materials:

Site ID: 537411  
Operable Unit ID: 1286047  
Operable Unit: 01  
Material ID: 2291631  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .25  
Units: Not reported  
Recovered: Not reported  
Oxygenate: Not reported